

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 06/18/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/14/12 – 0700, 06/21/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> • Ceresco Dam: upstream portage observed being constructed. • Ceresco Dam boom: observed crews removing debris. • Ceresco Dam: sheen observed. • Ceresco Dam: rainbow sheen observed on downstream side of boom. • Ceresco Dam: sheen observed bubbling up and going over dam. • Ceresco Dam: buoys deployed. • C0.4 Boat launch: sheen observed after boat launched. • MP5.6 LDB: sheen observed. • MP5.63 LDB: vegetation accumulating. • Observed well installation below Ceresco Dam. • MP29.25: Poling crew observed. • MP30.0 LDB: observed crew performing ring test. • MP30.0 LDB: sheen observed around boat when we docked. • MP30.8 LDB: sheen observed. • MP32.5: STRIKE poling team observed. • MP32.5 RDB: sheen observed around boat when we reversed. • MP34.0: STRIKE poling team. • MP36.25 RDB: overbank STRIKE team observed. • Morrow Lake Delta: poling crew observed. • Morrow Lake Delta: sheen sweep observed at E4 boom. • Morrow Lake: poling crew observed. • MP33.0: observed crew decontaminating test ring. • MP29.0: poling crew observed. 		
	Additional observations: None		
16:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			